




ENAPART



93 S Railroad Avenue Unit C
Bergenfield NJ 07621 USA
www.enapart.com
sales@enapart.com



Via del Canneto 35,
Borgosatollo, Brescia - Italia
www.enapart.it
vendite@enapart.it



Barbaros Mah. Ihlamur Bul. Ağaoğlu
My Newwork No:3/15 Ataşehir / İstanbul
www.enapart.net
satis@enapart.net



PRIVADA 10 B SUR #3908 COL.
ANZUREZ, C.P. 72530, PUEBLA, PUE
www.enapart.com.mx
sales@enapart.com.mx



Friedrich-Ebert-Anlage 36, 60325
Frankfurt am Main, Germany
www.enapart.de
anfrage@enapart.de



4 boulevard Carnot, 95400
villiers-le-bel, Paris, France
www.enapart.fr
sales@enapart.fr



65049, ОДЕСА, ВУЛИЦЯ ІВАНА
ФРАНКА, БУДИНОК 55, ПОВЕРХ 3
www.enapart.com.ua
sales@enapart.com.ua



MUNICIPIUL BUCUREȘTI, SECTOR 3,
B-DUL BASARABIA, NR.250, CORP P+5
www.enapart.ro
sales@enapart.ro



〒584-0023 大阪府富田林市若松町
東2丁目2番16号
www.enapart.co.jp
sales@enapart.co.jp



PLAZA NUESTRA SEÑORA DE LAS
NIEVES 12 ,LOCAL ,50012,ZARAGOZA
www.enapart.es
ventas@enapart.es



Складова база „Онгъл“, Склад А2, п.к.
4006, гр. Пловдив, България
www.enapart.bg
sales@enapart.bg



3 Austin Mews, High Street, Hemel
Hempstead, HP1 3AF , United Kingdom
www.enapart.co.uk
sales@enapart.co.uk

Burster

Enapart always strives to provide the competitive prices and timings of supplies for its customers. We sell only original equipment and spare parts, although we are not always the official distributor or manufacturer's dealer. All displayed trademarks and part numbers are the property of their respective owners.

BRAND'S PRODUCTS

Product	Description
1240-0.01	Calibration Resistor, 10 mΩ, Class 0.02
1240-0.1	Calibration Resistor, 100 mΩ, Class 0.02
1406/08	0,01OHM -10*10KOhm
2316-P001	Device and documentation software
2316-V0001	Milliohmometer RESISTOMAT
2316-Z001	19" rack mounting kit
2381-V001	Clamping device
2392-V001	temperature sensor
8402-6005	Miniatur - Druckkraftsensor
8402-6010	Load cell
8414-5050-V010	Subminiature Compression Load Cell with Overload Protection, 50 N
8431-6002	Precision miniature force sensor
8435-5200-N000S000	tension-pressure force sensor
8435-6001-N000S000	Miniature Tension and Compression Load Cell, 1000 N
8524-6005-S000S000	Precision Tension and Compression Load Cell, 5000 N
86413-5005-V501	Rotating Torque Sensor with Slip-Ring Transmission, 500 Nm
8712-50	Potentiometer
8713-10	Potentiometrischer Wegtaster
8741-5025-V501	DC/DC displacement sensor
91ABG	Adjusting a measurement chain
9243-IP65	Amplifier Module for Strain Gauge Sensors, IP65 Protection
2329-K001	measurement cable
9900-V165	MIN-D coupling plug
2328-Z001	Pyrometer
9900-V209	Coupling plug
9900-V609	9 pin D-sub socket
2329-P001	Labwindows Software
8661-5100-V0110	Precision Torque Sensor with Non-Contact Signal Transmission, 100 Nm
8690-5150-V426	Metal bellows coupling for torque sensors
2304-V005	RESISTOMAT digital ohmmeter
8524-6020-S000S000	Precision train-pressure force sensor
8600-2112-R-5010	converter
2382A	Einspannvorrichtung
2300-Z003	Transportkiste aus Holzwerkstoff
8661-4100-V0000	Dynamic precision torque sensor

Product	Description
8431-5500- N000S000	Sensor
8413-10N	LOAD CELL
4489-K	Digital Process Indicator for Strain Gauge Sensors
8740-5025	Sensor
8402-6050-S000S000	Load Cell
9235	In-line measuring amplifier
8712-100	Potentiometric Momentary
1240-0.0002	Calibration resistors
1240-0.0005	Calibration resistance
1240-0.001	Calibration Resistor
1240-0.002	Calibration resistance
1240-0.05	Calibration Resistor
1406	High-Precision Resistance Decade
8201-5100-H391A	Hochpräzisions-Drucktransmitter
8201-5800-N391A	Pressure sensor
8411-20	Load Cell
8413-20	Subminiature Compression Load Cell, 20 N
8411-5	Subminiature Tension and Compression Load Cell, 5 N
4592	Lederschutztasche
4498	1 Paar Bananenstecker mit Klemmanschluss
45DKD-4501	DAkKS Calibration Certificate for Pt100 Simulator Model 4501
Digiforce 9307	X-Y force / displacement controller
2329-Z004	Mounting kit
Calibration certificate for 4462-V200	Calibration Certificate for Bridge Amplifier Model 4462-V200
8402-6020-S000S000	Miniature Load Cell
99591-000A-0090100	Connection cable
2304-P001	Auswertesoftware für Typ 2304
2304-Z010	Calibration resistor
8712-10	potentiometer
8713-50	Potentiometrischer Wegtaster
4304.4001 (0225-1208)	Kombi-Netzfilter Schurter FKH2-50-1/I -
8524-6001	Zug-Druck-Kraftsensor
8741-5001-5010	Spring-Loaded DC/DC LVDT Displacement Sensor, 1 mm Range
8741-5025	Sensor
8741-5050	Inductive path sensor
1240-500	Constant resistor
8712-125 mm	Potentiometric Displacement Sensor, 125 mm Measuring Range
8661-5020-V0000	Precision Torque Sensor, 20 Nm, Contactless Transmission
1240-100	Calibration resistance
2304-V105	RESISTOMAT® High-Precision Automatic Inspection and Test Unit
8431-6005	Precision Miniature Tension and Compression Load Cell, 5 kN
8431-6010-N000S000	Precision miniature force sensor
8661-5010-V0000	High-Precision Rotating Torque Sensor, 10 Nm, Contactless Transmission
8580-V004	Load Introduction Button for Load Cells with M4 Thread

Product	Description
8435-5500-N000S000	Tension compression force sensor
86403-5160	torque sensors
99553-000A-0110030	connection cable, length 3 m
Display and Control unit for 8661-5010-V0000	Display and Control Unit for Precision Torque Sensor Model 8661-5010-V0000
23WKS-2316-V0000	Factory calibration certificate
23DKD-2316-V0000	RESISTOMAT 2316-V0000 type DAKKS calibration certificate
23WKS-2316-V0001	milliohmmeter
23DKD-2316-V0001	Calibration Certificate
2316-V0000	Kelvin-Messzangenpaar (groß)
8432-5050	Precision miniature force sensor
8524-6002-S000S000	Precision tension-compression force sensor
85DKD-85DX-6200	calibration certificate
93ABG	Measurement chain set-up
9310-V0000	Press-in, joining and clinching monitoring
9310-V0103 obsolete	Controller
99004	coupling plug
9900-K333	RS 232 cable
2316-Z002	External device program selecting switch
2316-Z003	External foot switch for measuring start/stop
2316-Z010	Calibration set
9900-V172	coupling plug
8415-5500	Miniature Load Cell
8738-DK830R	Incremental Path Button
8532-6001	Loadcell
8709-5025	Potentiometric Displacement Sensor
2385-V001	Kelvin pair of measuring tweezers (small)
8523-5100	Tension-compression sensor
9180-V0000	Digitalance
8432-6001	Precision Miniature Tension and Compression Load Cell with Overload Protection, 1 kN
9310-V0003	DIGIFORCE 9310 in combined table
4501	Decade Pt100 Simulator for Temperature Simulation
8741-5005-V511	Linear displacement transducer
2381	Dry clamping device
2388	wire protection strip
8661-5020-V0200	sensor
8661-5050-V0200	sensor
8627-5500	Static Torque Sensor with Flange Connection, 5000 Nm
8661-5200-V1110	Dynamic Dual Torque Sensor
8661-6001-V1112	Dual Torque Sensor
4462-V200	Hochpräzisions-Kalibrierquelle
9900-K342	Messleitungssatz
8661-5020-V1200	torque sensor
8661-5020-V3200	High-Precision Rotating Torque Sensor with USB Interface, 20 Nm

Product	Description
9405	DIGIFORCE® 9405 Process Controller for Monitoring Press-Fit and Joining Processes
9311-P100	DigiControl PC Software for DIGIFORCE® 9311
9310-Z001	Accessory
4462-V210	DIGISTANT® High-Precision Calibration Source for Voltage, Current, and Thermocouples
9181-V2000	Controlador
2386-V001	Measuring tips
2323	RESISTOMAT® Precision Resistance Meter
8709-5050	sensor
8435-6005	Druck-Kraftsensor
92ABG	Compensation of Measurement Chain for Sensor and Indicator Model 92xx
BUR400 616 Type 4462-V210	DIGISTANT® High-Precision Calibration Source for Voltage, Current, and Thermocouples
8661-5200-V0100	Präzisions-Drehmomentsensor
99540-000F-0520030	Cable
8580-V008	Load control button
8580-V012	Lasteinleitungsknopf
8524-6010-S000S000	Zug-Druck-Kraftsensor
2381-K006	Connection Cable for RESISTOMAT® Models 2316 and 2329
2316-V0000	Milliohmmeter RESISTOMAT with RS232 interface
8709-5200	displacement sensor
86-2800-5200	Rotating Torque Measuring Flange with Contactless Signal Transmission, 2000 Nm
Option 103562	Speed Measurement Option for Torque Sensors
Option 113627	Calibration Certificate for Torque Sensors
8690-5002-V1060	coupling
2316-Z011	calibration set
86413-5100-V501	Torque sensor
8435-6002	Compression Load Cell
8524-6020	Load Cell
DAkKS- Kalibrierschein für Milliohmmeter RESISTOMAT mit RS232	Accredited Calibration Certificate for RESISTOMAT Milliohmmeter
9311-V0002	DIGIFORCE® 9311 Process Controller for Monitoring Press-Fit and Joining Operations
9900-K453	interface converter
8661-5050-V0000	High-Precision Rotating Torque Sensor with Contactless Signal Transmission, 50 Nm
2381 50-1000mm	Clamping Device for Wire Resistance Measurement
1240-0.0001	Resistance
1240-1.0	Calibration resistor
1282-0.001	Präzisions-Hochlast-Messwiderstand 1 mOhm
Resistomat 2323	Portable Battery-Operated Microohmmeter
2323-Z001	Calibration Set for RESISTOMAT® 2323
23DKD-2323	DAkKS Calibration Certificate for RESISTOMAT® 2323

Product	Description
2387-V001	Kelvin Test Probes for Low-Resistance Measurements
1407	Precision Potentiometer for Angle and Position Measurement
8402-6010-S000S000	Miniature Compression Load Cell, 10 kN
9307-V0000	DIGIFORCE® 9307 Process Controller for Monitoring Press-Fit and Joining Processes
9300-Z003	Fixing kit for panel mounting
8710-100	Potentiometric Displacement Sensor
8431-5100-V201	Precision Miniature Tension and Compression Load Cell, 100 N
99209-591A-0090030	Connector Cable for DIGIFORCE® 9307, 9310, 9311
8227-5005-V334	Precision Resistor, 5 Ω
Interfaccia EtherCAT Vxxx1	Interface for EtherCAT in industrial automation
Interfaccia Profibus Vxxx2	Interface for Profibus in industrial automation
Interfaccia Profinet Vxxx3	Interface for Profinet in industrial automation
Interfaccia EtherNet/IP Vxxx4	Interface Module
Vx2xx for 9307	Resistance measurement
9307-P100	Software
8820-5350	Encoder Angular
8712-125	Potentiometric path sensor
42520	standard laboratory probe
8523-6001-S000S000	Tension and Compression Load Cell
9163-V00000	Digital Indicator
8417-5020-N000S000	Miniature Tension and Compression Load Cell
8413-5010-N0B0S000	Subminiature pressure sensor
9243	Amplifiers
9250-V000000	Universal Instrumentation Amplifier
8435-5500-V204	Pull-pressure force sensor
8402-6100-S000S000	Miniature Pressure Sensor
8661-5001-V000	Precision torque sensor
8710-150	Potentiometric
9186-V3100	Digital Indicator
9900-K336	9-Pin Sub-D Connector
9900-K361	converters
8402-6005-S000S000	Miniature Compression Load Cell
8661-4500-V0000	High-Precision Rotating Torque Sensor
9310-V0001	Digiforce Press-fit-, jointing and clinching monitor
9236-V300	3 Channel SG Amplifier
8712- 25	Potentiometric way sensor
8414-5050- B000S000	
8413-5010-N000S000	Subminiature pressure force sensor
8431-6005-N000S000	Precision Miniature Tension and Compression Load Cell
8431-6001-V000000D	Precision Miniature Force Sensor
99130	Connection cable
8661-5010-V0002	High-Precision Rotating Torque Sensor
8661-5010-V0102	Precision torque sensor
8661-5010-V0202	Precision torque sensor

Product	Description
8661-5010-V0402	Precision torque sensor
8526-6001-S000S000	Pressure force sensor
9236-V000	In-line measurement amplifier
8432-6002-N000S000	Precision Miniature Tension and Compression Load Cell with Overload Protection
8416-6005-N000S000	Ultra-Miniature Compression Load Cell
8431-5200- N000S000	Precision Miniature Tension and Compression Load Cell
8511-5200 range 200N	Miniature bending beam force sensor
8511-5020 range 20N	Miniature Bending Beam Load Cell
8432-5100-V000000A	Precision Miniature Force Sensor
8661-5005-V0000	Precision Torque Sensor
8402-6010- N000S000	Miniature Compression Load Cell
8713-25	Precision Potentiometric Displacement Sensor
8524-6050-N000S000	Precision Tension and Compression Load Cell
8524-6050-S000S000	Precision Tension and Compression Load Cell
8435-6002-N000S000	Pull pressure force sensor
8431-6002-N000S000	Precision miniature force sensor
8431-6002-N00ES000	Precision miniature force sensor
84WKS-84DZ-6200	Factory calibration certificate
84DKD-84DZ-6005	Factory calibration certificate
8523-5100-S000S000	Pull pressure force sensor
8431-5050- N000S000	Precision Miniature Tension and Compression Load Cell
1240-2	Calibration resistance 2 ohms
8510-5020-N000S000	Miniature bending beam force sensor
8690-5150-V26260	metal bellows coupling
8695-5150-V26260	metal bellows coupling
9311-V0003	DIGIFORCE 9311 in combined table/panel housing
8523-5500-N000S000	Pull pressure force sensor
1240-1	Calibration resistance 1 ohm
12DKD-1240	DKD calibration certificate
12WKS-1240	Factory calibration certificate
85043-1 MN	Precision force sensor
8438-6001-N000S000	Miniature ring force sensor
8719-5200	Potentiometric Displacement Sensor
8402-6020- N000S000	Miniature Compression Load Cell
8435-6005-N000S000	Miniature Tension and Compression Load Cell
7281-V0000	High precision calibration device
2382L	Einspannvorrichtung
Type:2381-V001	jig
23DKD-2304	DKD/DAkKS Calibration Certificate for RESISTOMAT® 2304
23WKS-2304	Factory Calibration Certificate for RESISTOMAT® 2304
42DKD-F	DKD/DAkKS Calibration Certificate for Force Measurement Devices
9941	Coupling plug
8661-4500-0000	High-Precision Rotating Torque Sensor
9900-V539	12-Pin M16 Connector

Product	Description
8432-5050-N0B0S000	Precision Load Cell
8438	Miniature Ring Load Cell
9900-K349	USB connection cable
8431-6005-N00ES00C	Precision miniature force sensor
8431-6005-N000S00C	Precision miniature force sensor
8524-6010-N000S000	precision tensile compressive force sensor
8524-5500-S000S000	Load Cell
8524-6002-V400	Load Cell
8661-5050-V0010	High-Precision Rotating Torque Sensor with USB Interface
8661-5050-V0110	High-Precision Rotating Torque Sensor with USB Interface
8661-5100-V0000	High-Precision Rotating Torque Sensor
8661-5050-V1000	precision torque sensor
8661-5002-V0000	High precision rotating torque sensor
99540-000F-0520050	Connecting Cable for Torque Sensors
99539-000F-0520050	12-Pin M16 Connecting Cable
8695-5002-V06080	Metal Bellows Coupling
8695-5010-V06140	Metal Bellows Coupling
8695-5010-V08140	Metal Bellows Coupling
8695-5060-V26140	Metal Bellows Coupling
8695-5010-V08190	Metal Bellows Coupling
8695-5060-V26190	Metal Bellows Coupling
8695-5060-V26240	Metal Bellows Coupling
1240-200	Calibration resistor
8438-6100-N000S000	miniature ring force sensor
9250-V000010	Amplifier module for DMS
9251-V3000	PROFINET Feldbus-Controller
9163-V04100	Precision Bridge Amplifier
4291-0	coupling plug
8526-6500-NXR0S000	pressure force sensor
99643-000A-0570030	interconnect cable
45WKS-4501	Factory Calibration Certificate for Decade Pt100 Simulator Model 4501
2381-K001	Precision Resistor
DAkKS Calibration Certificate for 8661-5050-v1000	Calibration certificate
DAkKS Calibration Certificate for 8661-5002-v0000	DAkKS Calibration Certificate for High-Precision Torque Sensor Model 8661-5002-V0000
DAkKS Calibration Certificate for Burster RESISTOMAT 2316	DAkKS Calibration Certificate for Burster RESISTOMAT 2316
8690-5010-V-08-14-0	8690 Series Mechanical coupler Burster
86DKD-LR-5200	DAkKS Calibration Certificate for Torque Sensor Model 8661-5200
8661-Z002	Mounting block for torque sensors
8695-5030-V15140	Metal bellows coupling for torque sensors
86E	Metal bellows coupling for torque sensors
8821-3600-V100	Incremental Rotation Sensor
2329-Z006	Connection Cable for RESISTOMAT® 2304

Product	Description
23DKD-2329	DKD calibration certificate for RESISTOMAT type 2329
23WKS-2329	Factory calibration certificate for RESISTOMAT type 2329
8511-5020-N000S000	bending beam - force sensor,
84DKD-84DZ-5500	Tension Compression Load Cell
8526-6005-N000S000	Compression load cell
8526-6005-S000S000	Compression load cell
8500-6500-K450	Compression force sensor
2329	resistance meter
8511-5050-N000S000	Miniature bending beam force sensor
2316-V001	Resistance measuring device
8400-B001-6001	PEDAL LOAD CELL FOR PEDAL OPERATING FORCES
8695-5030-V15190 / 86E	metal bellows coupling for torque sensors
8524-6020-S0B0S000	Precision tension-compression force sensor
8523-5200-N000S000	Load cell
8400-B001-6002	Pedal Load Cell for Pedal Operating Forces
7281-V0001	Mobile High-Precision Calibrator and Testing Device
8661-Z001	Mounting block for torque sensors
8661-Z003	Mounting block for torque sensors
8526-6010-SFB0S000	Pressure force sensor
8526-6100-SFB0S000	Pressure force sensor
8695-5060-V26320	metal bellows coupling for torque sensors
8695-5060-V15190	metal bellows coupling for torque sensors
8695-5030-V15110	metal bellows coupling for torque sensors
8695-5002-V06110	metal bellows coupling for torque sensors
8695-5030-V26110	metal bellows coupling for torque sensors
8695-5002-V06060	metal bellows coupling for torque sensors
8695-5002-V06050	metal bellows coupling for torque sensors
8695-5010-V06190	Metal Bellows Coupling
8712-10 /Sn: 87 16470205	Potentiometric way sensor
8427-6010-N000S000	Low cost tension pressure sensor
8656-5050-V01020	torque sensor
8201-5010-N391A	precision pressure transmitter
8526-6020-S000S000	Precision pressure force sensor
8709-5250	Potentiometric displacement sensor
8451-6100-N000S000	Press Load Cell for Hand and Automatic Operated Presses
8661-6001-V1212	high precision torque sensor
4420-V001	UNIVERSAL CALIBRATOR
8524-6005-NF00S000	Precision Tension and Compression Load Cell
9311-V0102	Digital Process Indicator
9311-V0103	DIGIFORCE® X/Y monitoring
8627-6001	torque sensor, non-rotating,
8552-6005-B000SEE0	Precision Compression Load Cell
8431-5100-NLB0S000	Precision Load Cell
8432-5020-N000S000	Precision miniature force sensor
2381-K003	RESISTOMAT connection cables

Product	Description
8526-6050-S000S000	Miniature Compression Load Cell
8526-6001-SB00S000	compressive force sensor
8416-5500-N000S000	Ultra-Miniature Load Cell
8739-5010-V302	LVDT Displacement Sensor with IN-LINE Amplifier
8417-5500-N000S000	Miniature Tension and Compression Load Cell
8431-5100-N000S000	Precision Miniature Tension and Compression Load Cell
8526-6100-S000S000	Compression Load Cell
8526-6100-S0J0S000	Compression Load Cell with Standardized Output Signal
8432-5200-N000S000	Precision miniature force sensor
8432-5200-N00ES000	Precision miniature force sensor
8500-B002-6030	Precision Compression Load Cell
99540-000E-0270030	connection cable
99540-000B-0270030	Compression Load Cell
99163-540A-0150030	connection cable
1240-5	Constant resistor
8402-6050-N000S000	Compression Load Cell with Standardized Output Signal
Model 2316-V0001	Milliohmmeter RESISTOMAT for Production and Laboratory
8661-5001-V2100	High-Precision Torque Sensor
99539-000F-0520030	Connecting cable
8695-5002-V08100	Precision Compression Load Cell
8695-5002-V05100	Metal Bellows Coupling
8719-5050-V001	Potentiometric Displacement Sensor
8524-6002-S000S400	Precision Tension and Compression Load Cell
8739-5005-V503	Inductive Displacement Sensor with IN-LINE Amplifier
9206-V0001	USB Sensor Interface for Strain Gauge, Potentiometric, DC/DC, and Pt100 Sensors
8580-V024	touch probe
9307-V0101	DIGIFORCE® 9307 Press-Fit Control
9307-V0201	DIGIFORCE® 9307 Press-Fit Control
8719-5300-V001	Potentiometric Displacement Sensor
99540-000F-0520100	Metal Bellows Coupling
8661-5020-V3100	High-Precision Rotating Torque Sensor
0093-0741	power card for 9307-V0101
1282-0.1	Precision High Capacity Resistors
12DKD-1282	Calibration certificate with accreditation symbol (DAkkS)
12WKS-1282	factory calibration certificate
4489-J	DIGISTANT® Precision Calibrator
1240-10 Ohm	Calibration resistance
8709-Z001	Mounting Accessory for Displacement Sensors
8661-5200-V0000	High-Precision Rotating Torque Sensor
8415-6005-NG00S000	Miniature Compression Load Cell
8415-5200-NG00S000	Miniature Compression Load Cell
8645-5005	Contactless Rotary Torque Sensor
8645-z003	Clamp for Torque Sensor Model 8645 (up to 17.5 N·m)
8201-5050-H021A	High-Precision Pressure Transducer

Product	Description
2317-V0000	Micro Ohmmeter
8431-6020-N000S000	Precision Miniature Tension and Compression Load Cell
8415-5200-BGF0S000	miniature compression force sensor
9236-V400	Four-channel in-line measurement amplifier for DMS sensors
99209-580A-0110002	adapter cable
7281-Z001	Power supply for 7281
7281-Z002	Aluminum Case for TRANS CAL 7281 and Accessories
7200- SUITCASE	aluminum case
7281-P101	Single user license for TRANS CAL 7281
72WKS-7281-00	ISO/factory calibration for TRANS CAL type 7281
72DKD-7281-00	Calibration certificate with accreditation symbol (DAkkS) for TRANS CAL type 7281.
8738-DK812R5	High-Precision Incremental Displacement Transducer
8709-5150	Mounting Accessory for Displacement Sensors
8709-Z002	Mounting Accessory for Potentiometric Displacement Sensor
8741-5050-V302	Inductive Displacement Transducer with Integrated Amplifier
8414-5050-N000S000	miniature compression force sensor
8526-5200-N000S000	Compressive force sensor
86413-5005	Torque transducer
2381-K006 / connection cable for 2381	cable de connexion
8655-5160-V0001	Rotating Torque Sensor with Integrated Speed Measurement
1240-0.005	High-Precision Calibration Resistor
8656-5050-V00020	Precision Rotating Torque Sensor
8427-5200-N000S000	Low-Cost Tension and Compression Load Cell
8712-150	Potentiometric Displacement Transducer
2354-6020-V0310	Precision Resistor
8432-5020-N000S010	Compressive force sensor
8416-5100-N000S000	Sensor
8402-6005-N000S000	Sensor
8526-6050-N0T0S000	Load cell
8526-5500-N0T0S000	Compressive force sensor
8526-6002-N0T0S000	Compressive force sensor
8526-6005-N0T0S000	Compressive force sensor
8526-6010-N0T0S000	Compressive force sensor
8526-6020-N0T0S000	Compressive force sensor
1240-20	Calibration resistance
7200-CASE	aluminum case
8402-6002-S000S000	Miniature Compression Load Cell
8524-6001-S000S000	Precision Tension and Compression Load Cell
5501-Z004	Mounting set
8552-5500...6025	Load cell
9307-OPT-VXXX1	DIGIFORCE® 9307 Option VXXX1
9307-OPT-VXXX2	DIGIFORCE® 9307 PROFIBUS Interface Option
9307-OPT-VXXX3	DIGIFORCE® 9307 EtherNet/IP Interface Option
9307-OPT-VXXX4	DIGIFORCE® 9307 EtherCAT Interface Option

Product	Description
9307-OPT-VX1XX	DIGIFORCE® 9307 Analog/Incremental Interface Option
9307-OPT-VX2XX	DIGIFORCE® 9307 PROFINET Interface Option
93ABGIT	Calibration of the measurement chain
4462-OPT-VX1X	DIGISTANT® 4462 Thermocouple Simulation Option
4462-OPT-VXX1	DIGISTANT® 4462 Extended Voltage/Current Range Option
4485-V001	Giunto
8526-6100-N000S000	Load cell
2386-V803	Electric tweezers
8402-6005-SLBZS000	miniature compression force sensor
8416-5050-N000S000	Load cell
8432-5500-N000S000	LOAD CELLS
8416-5020-B000L000	
8524-6002- N000S000	Load cell
8526-6020-N000S000	
8416-5020-N000S000	
8416-OPT-BXXXXXX	
8416-OPT-XXXXLXXX	
9206ABGIT	
9206-P100	
9206-P200	
8719-5450	
8719-5500	
8740-5050	
874X-OPT-V514	
4506	
4506S	
4591	
8402-6005-SL00S000	load cell
8432-5500-E000S000	
2354-6020-V0000	
8524-6001- N000S000	
8661-5020-V0102	
8661-OPT-VX1XX	Angular measurement option
8661-OPT-VXXX2	Key option on the spindle
8526-5500-N000S000	Compressive force sensor
8661-5020-V0202	Torque sensor
8431-6001-NG0ES000	
8661-5020	Torque sensor
8661-OPT-VX2XX	Angle/speed measurement option
92ABGIT	Calibration of the measurement chain:
9251-VX200	Bus Controller Module
8431-6001-N000S000	Miniature load cell
84XX-OPT-XGXXXXXX	
2381-Z-001	Calibration rod
8511-5200-N000S000	

Product	Description
7281-V0011	
8526-6010-S000S000	
8414-5010-N000S000	
8451-6100-N0B0S000	PRESSURE FORCE SENSOR
84XX-OPT-XXBXXXXX	
8739-5010-V501	
7281-OPT-VXXX1	
7281-P100	
7281-CASE	
72ABIGT	
85XX-OPT-XXBXXXXX	
85XX-OPT-XTTXXXXX	
1240-0.02	
1240-0.2	
1240-0.5	
8695-5002-V08080	metal bellows coupling
8415-6002-N000S000	Miniature Load Cell
8718 150	
8718-100	position sensor
8524-5500-S000S400	
8431-5200-N0B0S000	Precision Miniature Tension and Compression Load Cell
Type 2381	Thread tensioning bar
2390	
8661-5200-V0010	high precision torque sensor
9307-V0204	
8661-4050-V0200	
99163-540A-0520030	